



NAPSR – PHMSA Public Workshop on DIMP Implementation





National Association of Pipeline Safety Representatives
Office of Pipeline Safety

Don Stursma, Iowa





Topic Areas

- 1. Lessons learned from DIMP Inspections
- 2. Specific areas of concern to regulators






Lessons learned from Inspections

- The DIMP Implementation Team is beginning to receive inspection results from Inspectors and evaluate that data.
- Results from 70 DIMP Inspections have been evaluated so far. The data has been reviewed and coupled with our own inspection experiences to generate the topics presented today.
- More detailed analysis will be performed as we receive 2012 inspection results.



1208

Results of Inspections







Data

- Data quality is a common concern;
 - Outdated, incomplete, obvious errors.
 - Outdated data systems difficult to use or sort.
 - Data cleanup and scrubbing is often required.
- Reasonable balance between SME and hard data is important.
- Integration of data to identify existing and potential threats requires an appropriate level of resource allocation.
- When scrubbed data becomes available threat identification may need to be re-run.





Knowledge of Gas Distribution System

- SME qualifications, decisions and conclusions must be documented.
- How will field information be relayed into the DIMP.
 - May be necessary to modify field data acquisition forms and internal processes to incorporate new information and correct inaccurate information.
- Plan must account for identification and collection of missing and additional information needed to fill gaps.
- Plan must include procedure for recording new pipe data, including location and materials used.
 - Field data collection and acquisition forms may need to be enhanced.





Identify Threats to Integrity

- A DIMP must provide sufficient detail to address specific threats and risks in the Operator's unique operating environment.
- When evaluating risk, consideration must be given to applicable operating and environmental factors (e.g., paved areas, business districts, hard to evacuate) that can affect the Consequence of Failure (COF).
- Plan must include procedures to evaluate and obtain data from external sources that are reasonably available, and which may identify existing and potential threats.
- DIMP procedures must provide for the re-evaluation of threats and the identification of new or potential threats as new or improved information becomes availale.





Potential Threats

- Some Operators are struggling with potential threats:
 - Threats the Operator has not previously experienced (from industry or PHMSA information)
 - Threats that endangered facilities but have not resulted in a leak (e.g., exposed pipe, near misses).
 - Non-leak threats (overpressure, exposure, accessibility)
 - Threat from aging infrastructure





Identified Potential Threats

- Examples of potential threats often not being considered include:
 - over pressurization events;
 - regulator malfunction or freeze-up;
 - cross-bores into sewer lines;
 - materials with identified performance issues;
 - lack of access to facilities or causes of threats
 - Gophers, plastic eating bugs;
 - etc.





Evaluate and Rank Risks

- System subdivision for evaluating and ranking of risks must be sufficient to appropriately analyze risk(s) present in the Operator's unique operating environment.
- Geographical segmentation may be appropriate when systems are separated by space or a specific, predominate threat exists (e.g., flood, earthquake). However, if different materials are a predominate threat in a region, other segmentation may be needed to accommodate different failure rates.
- Operators must consider non-leak failures in analyzing risk.
 DIMP should address failures that do not result in a release (e.g., near miss) to identify potential threats.
- Risk ranking must include all risks to pipeline facilities.





Evaluate and Rank Risks (cont.)

- The risk ranking model results must be validated. One operator identified that the "COF" can be diluted by Frequency of Failure ("FOF") – a larger range for consequences was needed to get reasonable results.
- Plan must provide explanation of the process used to validate the data used in the risk ranking and to review the output of the risk ranking model for "reasonableness".
- The Plan (or "Model" used) must address risks specific to services as well as mains.
- When changes are made to a risk model, the risk ranking should be re-run and results incorporated into DIMP promptly.





Measures to Address Risks

- The Plan must provide a link between a specific risk (either a threat or consequence) and the measure to reduce that risk.
- The Plan must contain or reference an effective leak management plan unless all leaks are repaired when found. (If an Operator repairs all leaks when found, that must be stated or referenced in the DIMP.)
- Intervals must be established for the re-evaluation of measures implemented to reduce risks to gage their effectiveness and identify if the measure is appropriate.
- DIMP Models must rank proposed projects/replacements based on risk and not the cost.





Performance Measurement

- Each Measure Implemented to Reduce Risk must have a Performance Measure established to monitor its effectiveness.
- Operators must develop and monitor performance measures from an established baseline.
- A DIMP must include procedures for establishing baselines for Performance Measures (192.1007(e))
- Some Operator's Plans had "triggers" to initiate development of new or additional performance measures depending on program performance and the operating environment
- Operators have used a single performance measure to evaluate the effectiveness of multiple risk control measures.





Periodic Evaluation and Improvement

- A Plan must contain procedures for conducting periodic evaluations of its performance.
- If it is found necessary to make changes to the periodic evaluation procedure, the changes would be handled with revisions to the original procedure.
- Plans are expected to include procedures for notifying appropriate operator personnel of changes and improvements made to the plan.
- The Plan must provide for the incorporation of changes to facilities or to risk factors, such as:
 - Pipe replacement program changes risk ranking by removal of vintage pipeline facilities.
 - Flood control project reduces flood risk.





Report Results

- The DIMP must include (or reference) procedure(s) describing the collection and reporting of DIMP data (192.1009(g)) as part of the Annual Report to PHMSA.
- If a State agency exercises jurisdiction over the Operator's pipeline and requires reporting, the Plan must include (or reference) instructions for sending these reports the state pipeline safety authority as well.

This may seem duplicative of other reporting requirements, but the DIMP reporting rules were adopted before it was arranged for the information to be added to Annual Reports. Copying or referencing other reporting procedures should make this requirement easy to meet.





Records Required to be Maintained

- An operator must maintain records demonstrating compliance with the requirements of this subpart for at least 10 years (Including records not otherwise kept for 10 years).
- The Plan must describe how superseded plans and data will be maintained and kept secure
- Plans must include an adequate revision log that includes: the Plan effective date, revision dates, and a description of each revision
- Some Plans included statements that "all Company records were used in the development of the DIMP." Only the records actually used to develop and implement the DIMP should be referenced; otherwise <u>all</u> records must be kept for 10 years.





Other Comments

- Pre-DIMP risk reduction measures need to be incorporated into the DIMP plan.
- If risk evaluation concludes new or additional risk reduction measures are not needed to address a particular threat, that is acceptable but needs to be explained in the Plan.
- The DIMP rules may require something that is already being done in another context – copy it over or link to it.
- The Plan should culminate in a ranked/prioritized list of threats, risk reduction measures, and performance measures.
- Treat DIMP as a tool to analyze needs and progress, not as a regulatory exercise.





Thank you for Your Participation

"Opportunity is missed by most people because it is dressed in overalls and looks like work."

--Thomas Edison,
American inventor